



महाराष्ट्र शासन
सार्वजनिक बांधकाम विभाग



दुरध्वनीक्र. ०७१२-२५६५४४९

E-mail ID:-

div1nagpur.ec@mahapwd.gov.in

जा.क्र./ २०६३ / २०२६

कार्यकारी अभियंता, यांचे कार्यालय
सार्वजनिक बांधकाम विभाग क्र. १,
रेसिडेन्सी रोड, सदर, नागपूर

दि. ०३ / ०८ / २०२६

प्रति,

भगवानदास पुरोहित विद्यामंदिर,
चिचभवन, नागपूर

विषय - इमारत सुरक्षित असल्याचे प्रमाणपत्र देणेबाबत.

संदर्भ - १. आपले कार्यालयीन पत्र क्र BBPVM / CHB / ADMN / 2026-27 / 56

२. उपविभागीय अभियंता सार्वजनिक बांधकाम उपविभाग क्र.४ नागपूर यांचे पत्र क्र. १०२३/२०२६
दि. १०/०८/२०२६

संदर्भाकित पत्राच्या अनुषंगाने Bhavan's Bhagwandas Purohit Vidya Mandir at Bhavan's Bhagwandas Purohit Vidya Mandir, Chinchbhuvan, Nagpur या संस्थेच्या इमारत व परिसराची दि. १०/०८/२०२६ रोजी उपविभागीय अभियंता सार्वजनिक बांधकाम उपविभाग क्र.४ नागपूर यांनी मौका पाहणी केलेली आहे. संबंधीत संस्थेकडून मूळ प्रस्तावासोबत इमारत स्थिरता प्रमाणपत्र (Structural Stability Certificate) जोडलेले आहे. सदर प्रकरणात सोबत सादर करण्यात आलेले D.P.Mase (Chartered Engineer Nagpur) यांचे इमारत स्थिरता प्रमाणपत्राच्या अधिन राहून इमारत सुरक्षित असल्याचे प्रमाणपत्र देण्यात येत आहे.

सहपत्र - १) Building Safety Certificate.

(लक्ष्मीकांत प्र. राऊळकर)
कार्यकारी अभियंता
सार्वजनिक बांधकाम विभाग क्र. १
नागपूर.

प्रतिलिपी - उपविभागीय अभियंता सा.बा. उपविभाग क्र.४ नागपूर यांना माहितीसह अग्रेषित.

Abhutan
Smt. Anju Bhutani
Manager

DM/Letters/2026



PRINCIPAL
Bhavan's B. P. Vidya Mandir
Chinchbhuvan, Nagpur-15

Annexure D

BUILDING SAFETY CERTIFICATE

No. 8063/2026Dated : 03/09/2026

It is Certified that the existing building of **Bhavan's Bhagwandas Purohit Vidya Mandir, Chinchbhuvan, Nagpur** is having Block(s)/Floor(s) as per details below :

Details of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+6	-	-	-	-	-

The building is owned by **Bhavan's Bhagwandas Purohit Vidya Mandir, Chinchbhuvan, Nagpur** have compiled with the Building Safety requirements in accordance with National Building code Rule, and verified by the officers concerned of Public Works Division No. 1, Nagpur on 10/08/2026 in the presence of **Smt. Raji Srinivasan** (Principal, Bhavan's Bhagwandas Purohit Vidya Mandir, Chinchbhuvan, Nagpur) and that the building/premises is fit for occupancy for running school with effect from .11/08/2026 For a period of **1** year in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural Stability Certificate by Dr. D.P. Mase (Chartered Engineer) on Dt. 20/05/2026.
2. Fire Safety Certificate by MADC No. 3709/MIHAN/FIRE/2026 Dt. 06/08/2026.
3. Occupancy Certificate No. MADC/MIHAN/BP/692-A/1167 Dt. 02/03/2023.
4. Building Photos

Issued on 3 / 9/2026

at Nagpur by

Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


(Mukul Deshkar)
Sub Divisional Engineer
P. W. Sub Division No. 4
Nagpur


(Laxmikanth Raulkar)
Executive Engineer
Public Works Division No.1
Nagpur

To,
Principal,
Bhavan's Bhagwandas Purohit Vidya Mandir,
Chinchbhuvan, Nagpur .

ENDORSEMENT

The Building Safety Certificate issued by department stand cancelled and annulled due to Earth Quake, Fire or any other Natural Calamities.


Smt. Anju Bhutan
Manager
(Mukul Deshkar)
Sub Divisional Engineer
P. W. Sub Division No. 4
Nagpur




PRINCIPAL
Bhavan's B. P. Vidya Mandir
Chinchbhuvan, Nagpur-15


(Laxmikanth Raulkar)
Executive Engineer
Public Works Division No.1
Nagpur